



*Figure 1. Example of damaged nursery bags and geotextile and example of previous rehabilitation work still in good condition.*



*Figure 2. Examples of loose shell deposit to be removed before stabilisation with loffelstein retaining wall.*





*Figure 3. Example of damaged diamond mesh and damaged boardwalk to be sanded.*